# **MATERIAL IDENTIFICATION**

DOT SHIPPING NAME:

Hazardous Waste Solid N.O.S. (D007)

DOT HAZARD CLASS: UN OR NA NUMBER: Class 9 NA 3077 1990 EMERGENCY RESPONSE GUIDE

# **DOT EMERGENCY RESPONSE GUIDE 31**

# **POTENTIAL HAZARDS**

## FIRE OR EXPLOSION

Some of these material may burn, but none of them ignites readily.

# **HEALTH HAZARDS**

Contact may cause burns to skin and eyes.

Fire may produce irritating or poisonous gases.

Runoff from fire control or dilution water may cause pollution.

# **EMERGENCY ACTION**

Keep unnecessary people away.

Isolate hazard area and deny entry.

Self-contained breathing apparatus (SCBA) and structural firefighters,s protective clothing will provide limited protection.

CALL CHEMTREC AT 1-800-424-9300 FOR EMERGENCY ASSISTANCE. (Use Chemtrec Company Code "WORR") If water pollution occurs, notify the appropriate authorities.

## FIRE

Small Fires: Dry chemical, CO2, Halon, water spray or standard foam.

Large fires: Water spray, fog or standard foam is recommended.

Move container from fire area if you can do it without risk.

Do not scatter spilled material with high-pressure water streams.

Dike fire control water for later disposal.

## SPILL OR LEAK

Stop leak if you can do it without risk.

Small Dry Spills: With clean shovel place material into clean, dry container and cover, move containers from spill area.

**Small spill:** Take up with sand or other noncombustible absorbent material and place into containers for disposal.

Large Spills: Dike far ahead of liquid spill for later disdosal.

Cover powder spill wiuth plastic sheet or tarp to minimizing spreaing.

#### **FIRST AID**

In case of contact with material, immediatly flush eyes with running water for at least 15 minutes.

Wash skin with soap and water.

Remove and isolate contaminated clothing and shoes at the site.

NOTE: If this response guide is us	ed as an attachme	nt for shipping	documents,	enter	shipping
manifest number in block below.	WAD980738546	9/002	s sugar		
	WAD980738546_	16002			

(Shipping Manifest Number)

# **Material Safety Data Sheet**

D007 Recyclable Material

Recycler's Facility Name and Site Address:

World Resources Company

8113 West Sherman Street Phoenix, Arizona 85043

Tel: 1-602-233-9166 Fax: 602-936-9164

Issued: 3/18/94

Call CHEMTREC only in the event of emergencies during shipping that involve a spill, leak, fire, or accident (all calls are recorded)

For Emergencies During Shipping in the US or Canada, Day or Night, Call: CHEMTREC 800-424-9300 (Use CHEMTREC Company Code "WORR") For calls from other countries call: 202-483-7616 Collect

#### Section 1

Environmental Protection Agency (EPA) Waste Classification: D007

Generic Name: Chromium metal bearing sludge Chemical Family: Non-Ferrous metal particulates

Synonym: Metallic Residues From High Frequency Burning Table

#### PRODUCT -MATERIAL IDENTIFICATION

DOT Shipping Name: RQ, Hazardous Waste, Solid, n.o.s. (D007) DOT Hazard Class: 9; Packing Group: III **DOT Identification Number: NA 3077** 

**DOT Emergency Response Guide 31 Applies** 

### Section 2

# HAZARDOUS INGREDIENTS

Ingredient:	CAS Number:	Content %:	ACGIH-TLV	Toxicology:
Aluminum	7429-90-5	0-5	10 mg/m 3	No Data Available
Chromium	7440-47-3	0-15	0.5 mg/m 3	2.75 mg/kg (Rat, Oral)
Copper	7440-50-8	0-10	1.0 mg/m 3	0.35 mg/kg (Mouse, Oral)
Nickel	7440-02-0	0-10	1.0 mg/m 3	No Data Available
Zinc	7440-66-6	0-5	none established	No Data Available

#### Section 3

Description: Moist, Sandy consistency

Brown to Black colored

Water Content 10-20% by weight

Specific Gravity: 2.0 to 3.0 Solubility: Insoluble in water Density: 100 to 150 lbs/cu/ft

Incompatible Reactivity: Extreme heat sources.

Oxidants

Vapor Pressure: Insignificant

Stability: Avoid contact with acids, extreme heat

# PHYSICAL AND REACTIVITY DATA

Polymerization: Will not occur Boiling Point: Above 2000°C Melting Point: Above 1000°C

pH: 7.0 to 10.0

Odor: Nil

## Section 4

# AND EXPLOSION

Oxidation: Non-oxidizing Flashpoint: Nonflammable, under normal conditions Explosive: Non-explosive Special Firefighting Procedures: Dry Chemical

Product Decomposition. . . . (Due to Fire or Explosion): Hydrogen gas, ZnO ( under extreme external heat) Fire Diamond



TOXICITY

# Listed Carcinogen component: Chromium, Nickel Toxicology: See Sec. 2 (Chromium, Nickel ) Route of Entry: Inhalation and Ingestion

Section 6 HEALTH EFFECTS AND FIRST AID

Inhalation: Dust may irritate mucous membranes and upper respiratory tract. Remove to fresh air and treat symptoms.

Ingestion: Rare in industry. Induce vomiting (do not induce vomiting or give a liquid to an unconscious person) and call a physician.

Eyes: Dust may irritate eyes. Wash with copious amounts of water for 15 minutes, if effects persist, call a physician.

Skin: Dust may irritate skin, causing forms of eczema. Wash with soap and water.

Long-Term Effects: Chronic overexposure may affect the following target organs or body systems—blood, digestive, respiratory, lungs, liver, kidneys and skin.

Comments: Special attention should be given to employees with anemia, restricted respiratory abilities, lung cancer, permanent kidney damage and metal-sensitive skin or skin lesions.

# PRECAUTIONS FOR SAFE HANDLING

Handling: Good personal and industrial hygiene should always be practiced. It is recommended that personal protective equipment be used by personnel who will come in contact with the material. The equipment should include eye protection, respirator and

Storage: Keep covered and avoid conditions where wind could cause dispersal. Do not eat, drink or smoke where material is handled to avoid inhalation or ingestion. Store in a dry area under cover from rain.

Spills: Cleaning procedures should not create excessive dust. Vacuum when possible. Package material and send to World Resources Company at above address.

### Section 8

#### CONTROL MEASURES

Respiratory Protection: NIOSH-MSHA approved respirators as required. Other Protective Equipment: Coveralls are recommended, but not required.

Eye Protection: Safety Glasses recommended. Hand Protection: Gloves recommended.

### GENERATORS VERIFICATION

This MSDS is provided solely for informational purposes and no warranty or res	ponsibility is extended even though reasonable precautions
have been taken in the preparation of the data contained for this recyclable material listed on the attached Manifest Number:	rial. To the best of my knowledge this MSDS describes the
recyclable material listed on the attached Manifest Number: 7600 2 1	Telephone: (206) 382-8379 Date: 4-5-96
Company Name and Address: Alaskan Copper Works 62 Seattle WA 98/34	8 HANGEL &
Seattle WA 98134	OX IPA
	Signature

AZF-WRC 3/94

# **NOTICE**

TO: World Resource Company

8112 West Sherman Street Phoenix, Arizona 85043

From: Alaskan Copper Works

628 South Hanford Street Seattle, Washington 98134

SUBJECT: Land Disposal Restriction Notice

Manifest Number:	46002			
	4-5-96			
Date of Shipment:	7-5-76			

This shipment of material, which is being provided for recycling, is subject to the land disposal restrictions of 40 CFR, Part 268, Subpart D or the prohibitions specified in 268.32 or RCRA 3004(d). The applicable Land Disposal Restriction Information is provided in accordance with 40 CFR 268.7 and is shown below:

EPA Material	Regulated	Subcategory	Treatability	Treatment Standards	
Number	Constituent		Group	CFR Reference	Prohibition Level
D007	N/A	N/A	Nonwastewater	40 CFR 268.41 40 CFR 268.43	040 ann 1920
				•	

By: Gerald A. Thompson

Alaskan Copper Environmental Assistant